

Conservation



Project: External Repair and Maintenance Work

Description: Surveying Solutions Limited acted as Contract Administrator/CDM Co-ordinator for the re-roofing and external works to be carried out at this Category B listed property, on behalf of a private client. The works comprised re-roofing works to the main building, consisting of fully stripping the roof and re-slating in natural slate. External works were also carried out in the form of stone and chimney repairs, external decoration to parts of the property. The building was found to be a bat roost for several species, therefore, a Bat Licence was obtained and works required to be carried out between September and March.

Programme: To suit client deadlines

Client: Private Client

