


Schedule of Condition



- Project:** Schedule of Condition
- Description:** Surveying Solutions Limited were instructed to inspect the residential property at 6 Long Byres, Station Road, Broxburn, EH52 5RG and prepare a Photographic Schedule of Condition. The report was prepared to record the condition of the property in photographs and text in advance of works to build a retaining wall as part of the flood prevention scheme.
- Programme:** Summary Report within 24 hours and formal Report within 5 days
- Client:** Private Client

